
City of Baltimore Wet Smoke and Dyed	Page 1 of 1	
Sewershed: Gwynns Falls	Company: Savin	Date: <u>7/9/2009</u>
Test to be performed: Smoke Dyed Water X Dry ✓ Damp ☐ Wet ☐		Supervisor: <u>JAW</u>
Manhole_ID: S03WW_019MH	Test ID: <u>D1032-026038</u>	Notification Made: NA (Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Start of Survey	
0			Manhole	S03WW_019MH
0			Water Level	
72.5			Dye Test Not Visible	@ TF - toilet
72.5			Dye Test Not Visible	@ TF - downspout
72.5			General Observation	DOWN SPOUT DUMPS ONTO FRONT LA
100			General Observation	NO OTHER TAPS NEAR BY
100			Abandoned Survey	NEG DYE TEST